


C.B.R VALUE AT 0.1" PENETRATION—COMPACTED TO 95% STD. PROCTOR DENSITY



NOTES

1. FOR SOILS WITH C.B.R. LESS THAN THREE ASSUME C.B.R.=3
2. WHERE MECHANICAL ANALYSIS INDICATES THAT SOIL HAS MORE THAN 50% SILT OR MORE THAN 60% VERY FINE SAND AND SILT AN ADDITIONAL 150mm OF CLASS 'B' GRANULAR MATERIAL IS TO BE ADDED TO DESIGN DETERMINED FROM THESE CHARTS.

COMBINED THICKNESS OF ASPHALT AND GRANULAR MATERIALS (mm)